


To create the best connections 组装基本步骤示意图


- Insert tab and bend 90° degrees for most visible areas
● 插入扣孔，平折90°
- ▲ Insert tab and bend 90° degrees is best in some areas to ensure a tight connection
▲ 插入扣孔，旋转90°



Needle nose pliers are helpful for assembly
拼装工具




Metal sheet 金属部件




Notes: In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed. This product is not a toy. Keep out of reach of children.
请小心处理金属边料，以防刮伤


Assembly flow chart 拼装步骤




C




D




E



F



F



Rest insertion tabs should be bent inward 90 degree to lock F
按照图示安装上F，再把剩余折点向内平折90° 将F固定

